

Declassification Review by NGA/DoD

**QUT558**07

S E C R E T 212145Z

1965 MAY 21 21 587

**24** MAY 19

Office

File

ADMIN SEC BR

P&DS CSD

PSD-ICB

TID PID

PAG

DIAXX-4

NSA-LO DIA-AP

- CAMERA B 122 WAS USED IN MISSION 8018 FLOWN ON 20 MAY 65. COPIES RECEIVED PROCESSING WAS ACCOMPLISHED BY NAVRECONTECHSUPPCEN.
  - 2. ORIGINAL NEGATIVE:
    - A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- 9R SIDE: MANY FINE LONGITUDINAL SCRATCHES ARE PRESENT IN В. THE FIRST 240 FRAMES OF THE MISSION. A FEW OF THESE SCRATCHES, LOCATED AT 2.5". 4.6", AND 5.4" FROM THE OUTBOARD EDGE OF THE FILM PERSISTED THROUGHOUT THE REMAINDER OF THE MISSION. VERY FAINT IN BOARD EDGE STATIC IS PRESENT INTERMITTENTLY THROUGHOUT THE MISSION A HEAT SPLICE EXISTS IN FRAME 1279, AND A MANUFACTURING SPLICE 15 PRESENT IN FRAME 885.
- C. 9L SIDE: LONGITUDINAL SCRATCHES LOCATED 3.5" AND 5.0" FROM THE OUTBOARD EDGE OF THE FILM ARE PRESENT IN FRAMES 002 A HEAT SPLICE EXISTS IN THE FORMAT OF FRAME 1321, AND A MANUFACTURING SPLICE IS PRESENT IN FRAME 1608.
  - BOTH SIDES CONTAINED 2605 TITLED FRAMES EACH.
- E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS DURING THE MISSION.
  - 3. POSITIVE:
    - A. THE PI SUITABILITY IS GOOD.
    - B. THE PRINTING AND PROCESSING WAS GOOD.
- CLOUDS OBSCURED APPROXIMATELY 25 PERCENT OF THE MISSION PHOTOGRAPHY.

SECRET

eacar 1